
5.	ASSET AND WASTE MANAGEMENT COORDINATOR REPORT
Location:	Shire of Gnowangerup
Proponent:	N/A
Date of Report:	13 th September 2021
Business Unit:	Infrastructure
Officer:	Geoff Carberry - Asset and Waste Management Coordinator
Disclosure of Interest:	Nil

CURRENT STORAGE LEVELS AT THE END OF AUGUST

Airport Dam	95%
Central Dam	95%
Pistol Club Dam	98%
Complex Dam	90%
Wheatcroft dam	99%

Pumping is continuing to fill the Central Dam

AIRPORT CASA SURVEILLANCE INSPECTION

The CASA Surveillance Inspection report was received with two findings being made

- 1) Lack of NAIPS check prior to runway inspections as a check point on the inspection check list.
- 2) One line marking issue -Lead in line intersecting aiming point.

Both have been rectified to the satisfaction of CASA.

Dept of Water have indicated they are willing to supply two swipe card controlled "Stand pipes" one unit is complete with pump controller and camera the other requires a pump to be attached. DWER will initially supply 20 cards which can be increased if required.

Nutrient manage the control the cards for the systems.

BUILDING MAINTENANCE ACTIVITIES:

GNOWANGERUP:

- Airport Dam – refuel pump,
- Complex Dam second inlet pipe added
- Depot – admin reception area – place ducting around wall to hide power cords
- Pistol Club Dam – check and refuel pump throughout the day, erect new sign post
- Sporting Complex Dam – check and refuel pump
- Administration Office – (Council Chambers -remove window boxes, painting) – kitchen quote, assemble sanitizer unit machines for Anrie,
- Airport – replace windsock
- Grocock Street (CEO) – check pipe and repairs leaks
- Bowling Club Dam – check and refuel pump

- Community Park – basket ball court net removed, Public Toilets – clean and replace cistern flushing buttons.
- Star Building – measure for boxes
- Sporting Complex Creche – check for leaks
- Alymore Springs – repairs to BBQ shelter
- Swimming Pool – maintenance repairs to table top / paint and remove grates for painting, grouting tiles and check skimmer box
- Gunther Park – playground relocation plan
- Isuzu Ute GN.0036 – make bracket for sign for back of ute under OSH safety
- McDonald Street (DCEO) – check roof, stop the gurgling in drain pipe
- Groh House – Corbett Street – repairs to shower
- Wheatcroft Dam – turn pump on
- Grocock Street (CEO) – repairs to leaking pipe
- Ag Nutrien Building – check street camera – turn back on
- Cecil Street (Mechanic) – check pipes – blocked again
- Medical Centre – check ceiling, prop up for safety due to starting to fall down
- Library – erect new furniture

ONGERUP:

- Library – repairs to table trolley
- Weir Park – maintenance on playground equipment
- Septic Ponds – drop off gravel