4. INFRASTRUCTURE REPORT

**Location:** Shire of Gnowangerup

Proponent: N/A

**Date of Report:** 16<sup>th</sup> November 2021

**Business Unit:** Infrastructure

Officer: Yvette Wheatcroft - Manager of Works

Disclosure of Interest: Nil

## **PURPOSE OF THE REPORT**

To advise Council of the works carried out and items of interest during the month of October 2021.

### **INFRASTRUCTURE ACTIVITIES**

The construction crew continued to work on repairing the unsealed roads ready for harvest. We had two trucks down and one has been in Perth for most of October so this has made it logistically difficult to cover as many roads as we would have liked however, we have still managed to keep the graders gravel patching. Crystalline Civil worked for us maintenance grading during October to make up for the Ongerup maintenance position not yet filled.

Verge mowing has been more demanding than other years with the continuing rain, but we have managed to have all blocks mowed by the beginning of the fire season.

The construction program will begin in November with Rabbit Proof Fence gravel sheeting and the contracted work on Kwobrup Road. Rabbit Proof Fence Road will be finished by mid-November and Kwobrup Road is booked for sealing in December.

## **PROJECT STATUS**

2021-2022 road projects	Council Funds	State/Fed	Total Fund	% Complete
Roads to Recovery		Federal		
Rabbit Proof Fence Rd – gravel sheeting		\$128,474	\$128,474	0%
Boxwood Hill Ongerup Rd - resealing		\$132,479	\$132,479	0%
Magitup Road – gravel sheeting		\$131,938	\$131,938	0%
Regional Road Group State				
Kwobrup Road – widen and seal	\$183,600	\$367,000	\$550,600	0%
Borden Bremer Bay Rd – reseal 7km	\$60,334	\$126,666	\$187,000	0%
Council Funded				
Toompup South Rd – gravel sheeting	\$132,880		\$132,880	0%
Quinn Street RAV	\$72,089		\$72,089	0%
Corackerup Road – gravel resheet	\$133,630		\$133,630	0%
Gnop Tambellup Rd – pre widening works	\$42,600		\$42,600	0%

#### **MECHANICS REPORT**

**Komatsu Grader (Gnp)** – check over & wash, pull out leaking cylinder, strip apart replace spacer and dismantle circle guides

Ammann Vibrating Roller - wash & check over, fix hydraulic oil leak

Cat Loader - 5500 hour service

John Deere Grader (Borden) – pump up tyres, changed blades & resized blade bolts

**Isuzu small Tip Truck (Drainage)** - pull out PTO shaft & strip apart, take PTO shaft to Albany State Wide Bearings to match up, replaced PTO Shaft bearings & test

**John Deere Mower (Ongerup)** – repair cutting deck replace blades

**Toyota Kluger AWD Wagon – CEO** - 70,000 km service, vacuum and wash car

**Iveco AS500 Stralis Truck - GN.0044** –try to find reason for engine in limp mode, inspect wiring harness, socket EDC modules

**Dynapac Roller** - replace park brake switch

Side Tipping Trailer for Mack Truck - remove & replace damaged trailer socket

**Cat Grader (Ongerup)** – inspect machine

**Bomag Roller** – inspect machine

Husqvarna Mower (Ongerup) - replace broken mandrel (blades drives), replace blades

**John Deere Mower (Gnp)** - replace cutting blades, weld split in decking plates

**John Deere Backhoe (Ongerup)** - hydraulic cylinder ram seized, pull out hydraulic ram and send for repairs

**Cat Skid Steer -** remove & replace damaged hydraulic hose on slasher - take to Armadillo to make parts, replace burst O-ring on the hydraulic motor

Case Wheel Loader - repair hydraulic leak on steering hose

### P6000:

Himac Slasher - replace blades, burst O-ring on control valves Service chainsaw / whipper snipper / pole saw & water pumps

### **General Duties:**

Clean, tidy workshop
Albany – drop off & pick up varies vehicle parts
Replace gravel around the bays
Drop tyres off to tyre shop for repairs
Clean/tidy up used oil bays

## **ONGERUP GARDENER**

The main role of the Ongerup gardener is to maintain the town gardens, verge mowing and sporting facilities ovals and surrounds in Borden and Ongerup.

#### Other duties carried out in October 2021 included:

## Sign Installation/Maintenance:

- Boxwood Hill-Ongerup Road whipper snip around chevron signs
- Toompup Road South whipper snip around chevron signs

# **Remove Fallen Trees/Pruning:**

- Ongerup Town Hall remove fallen tree
- Stone Street Borden cut up fallen tree on footpath

#### Other duties included:

- Water sampling as per Health Department requirements
- Borden & Ongerup Street bins for weekly rubbish collection
- Push up Ongerup and Borden refuse sites
- Collect public toilet supplies from Gnowangerup
- Check septic ponds
- Clean up around the depot
- Staff Breakfast & Workforce Review Plan

## **WORKS AND DRAINAGE CREWS**

Continual checking of roads for hazards due to rainfall. Signs continually stood up and down as rainfall affected the road surface. Pumping water from low lying areas where possible.

Borden Bremer Bay Road – cart gravel repairs for gravel patching
Rabbit Proof Fence Road – repairing floodway crossing
Nightwell Road – gravel sheeting, repair crossover
Highdenup Road – gravel patching
Cecil Street & House Street – erect new bollards to stop trucks driving over the new kerbing

#### **Drainage Crew:**

Clean up chemical compound area at Gnowangerup Clean grates & unblock sumps around the Gnowangerup town site Assist mechanic to remove hydraulic ram from Ongerup Backhoe for repairs

Culvert Maintenance: Inspections and clearing of drains around the Shire road network

### Mowing/Slashing/Whipper snipping:

Gnowangerup town site – whipper snipping / slashing and mowing Walsh Street – slashing road verge ONeill Road – mulching Toompup Road South – slashing Ongerup Borden town sites – mow & spray weeds

**Verge Maintenance:** Gnowangerup / Ongerup & Borden town sites

## **Tree Pruning / Removal:**

Gnowangerup town site – tree pruning
Sandalwood Road – remove tree
Hart Road – remove tree
Denny Street – slash vacant block and clean drain to creek
Ongerup-Pingrup Road – remove tree
Borden town site – prune tree limbs

# **Bitumen Patching:**

Nightwell Road
Boxwood Hill-Ongerup Road
Hinkley Road
Old Ongerup Road
Tie Line Road
Ongerup-Pingrup Road
Gnowangerup-Tambellup Road
Gnowangerup town site

# Other duties included:

- Grease trap cleaning
- Septic tank cleaning
- Private works
- Gnowangerup Refuse Site maintenance
- Ongerup Refuse Site maintenance
- Road inspections around the Shire due to continuing rainfall throughout the month
- Pick up freight and deliveries
- Clean up yard around the depot
- Ongerup Cemetery slash and clean up branches
- Shift grader driver vehicles
- Carting gravel to Gnowangerup Depot for stockpiling
- Gnowangerup Complex dam remove pump
- Assisting Mechanic for plant repairs
- Workforce Review Plan meeting

# **GRADER MOVEMENTS – WORKING DAYS IN OCTOBER 2021**

Gnowangerup Grader – Maintenance Grading			
Grader	Road Name	Hours	
John - Gnowangerup	Highdenup Road	29	
P2016 & P2006	Magitup Road	10	
	North Stirling Road	31	
	New Country Road	14	
	Kelly Road	23	
	Total	107 hours	
		·	

Borden Grader – Maintenance Grading				
Grader	Road Name	Hours		
Alan - Borden	Pinnacle Road	5.5		
P2006 & P2003	Pendalup Road	6.5		
	Nightwell Road	6		
	Laurier Road	14		
	Gnp Depot - maintenance	1.5		
	Greaves Road	2		
	Wellstead Road	4.5		
	Toompup Road South	2		
	Haxby Road	2		
	Hart Road	3.5		
	Foster Road	10.5		
	Tie Line Road	4.5		
	ONeill Road	6.5		
	Park Road	9.5		
	Day Road	3.5		
	Oakdale Road	6		
	Rabbit Proof Fence Road - repairs	6.5		
	Total	94.5 hours		

### John

- 2 days RDO
- 3 days road checks & guideposts installation due to wet weather

#### Alan

- 1 day RDO
- 1 day RDO worked
- 1 day sick
- 1 day assisting works crew transporting plant
- 1 day road Inspections due to wet weather

NOTE: The Ongerup Grader driver position was not filled in October

# Standpipe usage

October - 5,500 litres

## Septic pump outs

October 2021 – 12000 litres

# **Grease trap pump outs**

October 2021 – 1750 litres

# Septic waste from outside the Shire.

October 2021 - 2000 litres

# Septic waste received from contractors.

October 2021 – nil